

# MONUMENT RECORD

S - 21



STATE OF INDIANA - COUNTY OF MONROE

SECTION 26, TOWNSHIP 8 NORTH, RANGE 2 WEST

## MONUMENT DESCRIPTION & REMARKS

IRON PIPE SET,

### RECOVERY TIE DRAWING



(•) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, \_\_\_\_\_ HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 19\_\_\_\_ A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:  
VAN BUREN

CORNER I.D.

S - 21

SECTION 26  
TOWNSHIP 8N  
RANGE 2W  
RS1D002227

# 23

# 27

# 25


# 35

AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74 SURVEY PARTY T. Daugherty - H. Sudbury

COMMENTS pipe placed flush in E of Road - it was not checked to North & South, but was check-chained East & West.

REFERENCE SKETCH ( use back if ness.)





SECTION 26TOWNSHIP 8NRANGE 2W

RSID 002227

# 23

NW, NW

NE, NW

NW, NE

NE, NE

SW, NW

SE, NW

SW, NE

SE, NE

NW, SW

NE, SW

NW, SE

NE, SE

SW, SW

SE, SW

SW, SE

SE, SE

2643.3

2643.3

Van Bu-321

# 35

## AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74SURVEY PARTY T. Daugherty - H. Sudbury

CONTENTS pipe placed flush in E of Road - it was not checked to North & South, but was check-chained East & West.

## REFERENCE SKETCH ( use back if ness.)

